

## XDL Rover I/O Firmware Release Notes, January 2017

### Version 1.12.0001, ID#1385, Jan 2017

<u>ID#</u>	<u>Description</u>
1552	Permits XDL Rover 2 to start correctly with low battery
1556	Turns Bluetooth module on and off properly
1558	Cleans up all GPIO access lines
1560	Improves LED behavior when signaling error states
1563	Corrects issue when recharging the battery

### Version 1.10.0001, ID#1337, Aug 2015

<u>ID#</u>	<u>Description</u>
1357	Improves Bluetooth connection to certain clients
1365	Longer button press required to turn Bluetooth OFF
1395	Better power management
1442	Use Bluetooth packet mode instead of stream mode
1452	Can now turn off Bluetooth and charge battery when running on internal battery

### Version 1.02.0039, Aug 2014

<u>ID#</u>	<u>Description</u>
985	Allows RX LED to flash when data is received
1064	Allows green LED to function properly with low battery
1122	Allows changing the RX channel with the power button
1242	Bluetooth LED correctly shows when it is not paired
1243	PWR LED now stays on when in Bluetooth Mode
1244	Improved RX LED function
1280	Improved power supply function
1285	Prevents radio from draining its battery so low it cannot be recharged
1291	Supports configuration with ADLCONF
1308	Supports battery recharging when plugged to external power
1350	ADLCONF: Fixed Serial Number field error
1351	ADLCONF: Improved wording in dialog box when uploading I/O FW into radio
1358	Bluetooth remains discoverable and in active mode indefinitely